

Annexure- D

BUILDING SAFETY CERTIFICATE

Dated: 11/09/2026

No.

It is certified that the existing building Govt High School Lalung (name of the building or premises) at Lalung - Kargil (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Two (02)	—	—	—	—	—

The building is owned/occupied by Govt High School Lalung (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of R&B division Kargil (Name of Department/ Govt.) on 14-September (date of inspection) in the presence of School Headmaster, & faculty members & N.E.C member (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 14-Sep. for a period of One years in accordance with rule and subject to compliance of the specific conditions as appended.

1. No alteration or structural change is made without prior approval from a registered Structural Engineer.
2. Proper maintenance of the building is carried out from time to time.
3. This certificate is issued based on visual inspection of the building as conducted.
- 4.

Issued on 14-September at 12:00 p.m. by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal:

Name:

Designation:

Name & Address of Department/ Office: R&B Division Kargil

Assistant Ex. Engineer (R&B) Sub. Division Mohd. Kargil

Assistant Engineer